Primary and Discontinuity Sensor Group Locations (KHLR)



AN/FMQ-23 Primary Sensor Group (KHLR RNWY 34)

No Secondary/Discontinuity Group at KHLR

Wind Sensor being changed to mechanical (awaiting CCB Action)